



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2015 - Swan and Canning Rivers

LGA/ Managing Authority	Water Body	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	Min No. Samples Rqd 2015-2016
City of Bayswater/ DPaW	River	EV3/523	Hind Reserve (Garratt Rd - Jetty)	2010-2015	74	60	B	96	42	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
City of Bayswater/ DPaW	River	EV3/541	East St Maylands Yacht Club	2010-2015	71	60	B	121	39	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
City of Belmont/ DPaW	River	EV3/517	Garvey Park (Faulteroy Ave)	2010-2015	77	340	C	250	102	Very High	Poor	Red	Management Action: Erect permanent warning signs - elevated bacterial levels rainfall events	13
City of Belmont/ DPaW	River	EV3/538	Belmont Park Beach	2010-2015	72	120	B	212	61	Very High	Fair (a)	Amber	Management Action: Erect permanent warning signs - elevated bacterial levels rainfall events	13
City of Belmont/ DPaW	River	EV3/539	Cracknell Park (Riversdale Rd)	2010-2015	74	85	B	127	49	Very High	Fair (a)	Amber	Management Action: Erect permanent warning signs - elevated bacterial levels rainfall events	13
City of Canning/ DPaW	River	EV3/542	Shelley Beach (Near Drain)	2010-2015	66	240	C	859	124	High - F/U	Poor	Red	Collect 10 rainfall (24-48hrs) & stormwater samples	13
City of Canning/ DPaW	River	EV3/547	Clontarf Bay (Cadets)	2010-2015	90	520	D	763	183	Moderate - F/U	Poor	Red	Collect 10 rainfall (within 24-48hrs) samples	5



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2015 - Swan and Canning Rivers

LGA/ Managing Authority	Water Body	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	Min No. Samples Rqrd 2015-2016
City of Melville/ DPaW	River	EV3/505	Bicton Baths	2010-2015	73	36	A	96	27	Moderate - F/U	Good (a)	Green	Collect 10 stormwater drain samples	13
City of Melville/ DPaW	River	EV3/507	Cunningham St (Applecross)	2010-2015	74	60	B	475	21	Moderate	Good	Green		13
City of Melville/ DPaW	River	EV3/532	Point Walter (Kiosk)	2010-2015	73	50	B	101	36	Low - F/U	Good	Green	Collect 10 stormwater drain samples	13
City of Melville/ DPaW	River	EV3/533	Point Walter (Boat Ramps)	2010-2015	73	50	B	123	33	Moderate	Good	Green		13
City of Melville/ DPaW	River	EV3/534	Waylen Bay (Scout Hall)	2010-2015	69	24	A	69	23	Low	Very Good	GREEN*	Annual Sanitary Inspection Review	5
City of Melville/ DPaW	River	EV3/540	Deep Water Point Beach (Near Jetty)	2010-2015	71	28	A	84	23	Moderate	Good (a)	Green		13
City of Perth	River	PR3/024	Point Fraser	2011-2015	74	270	C	322	100	Assessment Required	Not Avail	Amber	Provide DoH Sanitary Inspection Report	13
City of Perth	River	PR3/025	Barrack Jetty	2011-2015	74	20	A	55	26	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
City of Perth/ DPaW	River	PR3/022	Claisebrook	2011-2015	72	12	A	45	22	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
City of Perth/ DPaW	River	PR3/023	Trinity	2011-2015	73	310	C	656	135	Assessment Required	Not Avail	Amber	Provide DoH Sanitary Inspection Report	13
City of Perth/ DPaW	River	PR3/026	Mounts Bay Road	2011-2015	73	320	C	513	126	Assessment Required	Not Avail	Amber	Provide DoH Sanitary Inspection Report	13



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2015 - Swan and Canning Rivers

LGA/ Managing Authority	Water Body	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	Min No. Samples Rqrd 2015-2016
City of South Perth/ DPaW	River	EV3/511	Como Beach Jetty	2010-2015	68	24	A	152	10	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
City of South Perth/ DPaW	River	EV3/512	Narrows Bridge	2010-2015	88	350	C	25949	468	Assessment Required	Not Avail	Amber	Provide DoH Sanitary Inspection Report	13
City of South Perth/ DPaW	River	EV3/513	Coode St South Perth	2010-2015	88	230	C	309	93	Very High	Poor	Red	Management Action: Erect permanent warning signs - elevated bacterial levels rainfall events	13
City of South Perth/ DPaW	River	EV3/536	Como Beach South	2010-2015	81	125	B	520	63	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
City of South Perth/ DPaW	River	EV3/537	Como Beach North	2010-2015	81	290	C	3875	216	Assessment Required	Not Avail	Amber	Provide DoH Sanitary Inspection Report	13
City of South Perth/ DPaW	River	EV3/546	South Perth (Esplanade Beach)	2010-2015	92	135	B	208	65	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
City of Subiaco/ DPaW	River	EV3/528	Hackett Drive Crawley (Kiosk, Jett)	2010-2015	76	150	B	344	73	High - F/U	Good	Green	Collect 10 rainfall (within 24-48hrs) samples	13
City of Subiaco/ DPaW	River	EV3/530	Hackett Drive Crawley (Tree)	2010-2015	78	115	B	202	59	Moderate - F/U	Good	Green	Collect 10 rainfall (within 24-48hrs) & stormwater samples	13
City of Subiaco/ DPaW	River	EV3/543	Abrahams Reserve Beach	2010-2015	78	40	A	100	29	Moderate - F/U	Good (a)	Green	Collect 10 rainfall (within 24-48hrs) & stormwater samples	13



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2015 - Swan and Canning Rivers

LGA/ Managing Authority	Water Body	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	Min No. Samples Rqd 2015-2016
City of Swan	River	SW3/001	Fish Market Reserve – Boat Ramp							High - F/U	Not Avail	Red	Collect 10 rainfall (within 24-48hrs) & stormwater samples	13
City of Swan	River	SW3/002	Fish Market Reserve – St Vincents Beach							High - F/U	Not Avail	Red	Collect 10 rainfall (within 24-48hrs) & stormwater samples	13
City of Swan/ DPaW	River	EV3/519	Ray Marshall Park (First Ave)	2010-2015	88	290	C	5741	140	Very High	Poor	Red	Management Action: Erect permanent warning signs - elevated bacterial levels rainfall events	13
City of Swan/ DPaW	River	EV3/520	Middle Swan Reserve	2010-2015	107	680	D	12090	228	Very High	Very poor	RED*	Annual Sanitary Inspection Review	5
Shire of Peppermint Grove	River	EV3/503	Keane St Beach (50M S Irvine St)	2010-2015	58	75	B	158	45	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
Town of Bassendean	River	EV3/548	Point Reserve (Nth Jetty)	2010-2015	62	640	D	492	165	High - F/U	Very Poor	Red	Collect 10 rainfall (within 24-48hrs) & stormwater samples	13
Town of Bassendean/ DPaW	River	EV3/522	Sandy Beach Reserve	2010-2015	62	280	C	5166	127	Moderate - F/U	Poor	Red	Collect 10 rainfall (within 24-48hrs) samples	13
Town of East Fremantle/ DPaW	River	EV3/545	Preston Point - John Tonkin Park	2010-2015	34	55	B	158	31	Moderate - F/U	Good	Green	Collect 10 stormwater drain samples	13
Town of Mosman Park/ DPaW	River	EV3/544	Johnston Street - Hill Tce Beach	2010-2015	62	4	A	31	17	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	5