



## Recreational Waters Bacterial (Enterococci) Sampling Program Site Status Overview (October 2014) - Perth Metropolitan Coastal Beaches

LGA	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	SAC Key Factors	SAC Status Comments	Provisional Class	Provisional Colour	Min No. LGA Samples Required 2014-2015
WANNEROO	EV3/764	Two Rocks (Sovereign Park)	2009-2014	90	2	A	20	10	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	5
WANNEROO	EV3/763	Two Rocks - Leemans Landing	2009-2014	90	20	A	2173	10	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	12
WANNEROO	EV3/762	Yanchep Lagoon	2009-2014	92	20	A	116	10	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	12
WANNEROO	EV3/739	Quinns Rock	2009-2014	71	34	A	330	10	Moderate - F/up	Rainfall	Collect 5-10 rainfall (24-48hrs) samples	Good (a)	Green	12
WANNEROO	EV3/759	Mindarie (Claytons Beach)	2009-2014	67	6	A	34	14	Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	5
JOONDALUP	EV3/736	Burns Beach	2009-2014	73	50	B	206	10	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good	Green	12
JOONDALUP	EV3/768	Ocean Reef Boat Harbour Entrance (Beach)	2013-2014	21	40	A	143	21	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	12
JOONDALUP	EV3/767	Ocean Reef Boat Harbour Beach	2013-2014	21	240	C	1907	148	Outstanding		Provide DoH Sanitary Inspection Report	Fair (a)	Amber	12
JOONDALUP	EV3/766	Ocean Reef Boat Harbour (Platform)	2013-2014	21	90	B	290	45	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	12
JOONDALUP	EV3/765	Key West	2013-2014	21	24	A	77	18	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	12
JOONDALUP	EV3/732	Mullaloo Beach	2009-2014	72	9	A	39	16	Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	5
JOONDALUP	EV3/731	Pinnaroo Point	2009-2014	75	145	B	681	75	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	12



## Recreational Waters Bacterial (Enterococci) Sampling Program Site Status Overview (October 2014) - Perth Metropolitan Coastal Beaches

LGA	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	SAC Key Factors	SAC Status Comments	Provisional Class	Provisional Colour	Min No. LGA Samples Required 2014-2015
JOONDALUP	EV3/730	Hillarys North Swim	2009-2014	76	40	A	608	30	Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	12
JOONDALUP	EV3/729	Hillarys Middle Swim	2009-2014	76	70	B	156	42	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good	Green	12
JOONDALUP	EV3/728	Hillarys South Swim	2009-2014	75	145	B	343	71	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	12
JOONDALUP	EV3/725	Hillarys South Break	2009-2014	73	22	A	69	19	Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	12
JOONDALUP	EV3/758	Sorrento Beach (Surf Club)	2009-2014	67	3	A	27	14	Moderate - F/up	Rainfall	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green	5
STIRLING	EV3/724	Watermans Beach	2007-2013	56	2	A	17	11	Moderate - F/up	Rainfall	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green	5
STIRLING	EV3/723	Hamersley Pool	2009-2014	65	10	A	40	10	Moderate - F/up	Rainfall	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green	5
STIRLING	EV3/722	Mettams Pool	2009-2014	75	36	A	490	10	Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	5
STIRLING	EV3/721	Trigg Island	2009-2014	61	8	A	39	18	Moderate - F/up	Rainfall	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green	5
STIRLING	EV3/757	South Trigg Beach	2009-2014	67	7	A	38	10	Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	5
STIRLING	EV3/755	Scarborough Beach North	2009-2014	63	2	A	28	10	Moderate - F/up	Rainfall	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green	5
STIRLING	EV3/720	Scarborough Beach	2009-2014	68	2	A	18	10	Moderate - F/up	Rainfall	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green	5



## Recreational Waters Bacterial (Enterococci) Sampling Program Site Status Overview (October 2014) - Perth Metropolitan Coastal Beaches

LGA	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	SAC Key Factors	SAC Status Comments	Provisional Class	Provisional Colour	Min No. LGA Samples Required 2014-2015
STIRLING	EV3/756	Scarborough Beach South	2009-2014	76	6	A	34	13	Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	5
CAMBRIDGE	EV3/719	Floreat Beach	2009-2014	51	8	A	37	13	Low	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Very Good	Green	5
CAMBRIDGE	EV3/754	City Beach North	2009-2014	59	32	A	1185	16	Low	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Very Good	Green	5
CAMBRIDGE	EV3/718	City Beach	2009-2014	38	4	A	30	16	Low	Rainfall	Collect 5 rainfall (within 24hrs) samples	Very Good	Green	5
NEDLANDS	EV3/717	Swanbourne Beach	2009-2014	69	60	B	243	30	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	12
COTTESLOE	EV3/753	Cottesloe North	2009-2014	70	24	A	154	10	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	12
COTTESLOE	EV3/716	Cottesloe Beach	2009-2014	71	45	B	115	31	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	12
FREMANTLE	EV3/715	Leighton Beach	2009-2014	67	2	A	20	10	Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	5
FREMANTLE	EV3/714	Port Beach	2007-2012	60	2	A	30	10	Moderate - F/up	Rainfall	Collect 5 rainfall samples	Good (a)	Green	5
FREMANTLE	EV3/713	Fremantle Swimmers Beach	2009-2014	70	3	A	27	14	Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	5
FREMANTLE	EV3/711	South Beach	2009-2014	72	75	B	190	41	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good	Green	12
COCKBURN	EV3/710	C.Y.O'Connor Beach	2009-2014	71	80	B	191	45	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	12



## Recreational Waters Bacterial (Enterococci) Sampling Program Site Status Overview (October 2014) - Perth Metropolitan Coastal Beaches

LGA	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	SAC Key Factors	SAC Status Comments	Provisional Class	Provisional Colour	Min No. LGA Samples Required 2014-2015
COCKBURN	CK3/997	Port Coogee	2011-2014	60	85	B	8597	41	Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good	Green	12
COCKBURN	EV3/709	Coogee Beach	2009-2014	67	3	A	26	14	Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	5
COCKBURN	EV3/752	Jervoise Bay Beach	2009-2014	71	65	B	4522	31	Moderate	Rainfall	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green	12
KWINANA	EV3/706	Naval Base	2009-2014	69	30	A	118	10	Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	12
KWINANA	EV3/751	Kwinana Beach	2009-2014	67	12	A	45	16	Moderate - F/up	Rainfall	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green	12
ROCKINGHAM	EV3/701	Rockingham Beach	2009-2014	70	125	B	389	63	Low	Rainfall	Provide DoH stormwater drain monitoring results	Good	Green	12
ROCKINGHAM	EV3/750	Palm Beach (Next to Jetty)	2008-2013	65	2	A	24	14	Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	5
ROCKINGHAM	EV3/760	North Hymus	2009-2014	72	70	B	177	40	Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good	Green	12
ROCKINGHAM	RK3/028	Bent Street	2012-2014	28	115	B	288	60	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	12
ROCKINGHAM	RK3/012	Waikiki Beach	2009-2014	94	28	A	85	20	Low		Annual Review	Very Good	Green	5
ROCKINGHAM	RK3/027	Secret Harbour Surf Club	2009-2014	80	18	A	57	19	Low		Annual Review	Very Good	Green	5